## **Massachusetts Cultural Resource Information System**

## **Scanned Record Cover Page**

Inventory No: CON.1812
Historic Name: Burke Garage

**Common Name:** 

Address: 55 Old Bedford Rd

City/Town: Concord

Village/Neighborhood: Merriam's Corner

**Local No:** 

Year Constructed: c 1908

Architect(s):

Architectural Style(s): No style
Use(s): Out Building
Significance: Architecture

CON.C: Minute Man National Historical Park

Area(s): CON.BL: Lower Old Bedford - Virginia Roads Area

CON.EC: Minute Man National Historical Park

Nat'l Register District (10/15/1966); Nat'l Historic

**Designation(s):** Landmark (10/15/1966); Nat'l Register District

(11/29/2002)

Roof: Asphalt Shingle

Building Materials(s): Wall: Wood; Wood Shingle

Foundation: Concrete Unspecified



The Massachusetts Historical Commission (MHC) has converted this paper record to digital format as part of ongoing projects to scan records of the Inventory of Historic Assets of the Commonwealth and National Register of Historic Places nominations for Massachusetts. Efforts are ongoing and not all inventory or National Register records related to this resource may be available in digital format at this time.

The MACRIS database and scanned files are highly dynamic; new information is added daily and both database records and related scanned files may be updated as new information is incorporated into MHC files. Users should note that there may be a considerable lag time between the receipt of new or updated records by MHC and the appearance of related information in MACRIS. Users should also note that not all source materials for the MACRIS database are made available as scanned images. Users may consult the records, files and maps available in MHC's public research area at its offices at the State Archives Building, 220 Morrissey Boulevard, Boston, open M-F, 9-5.

Users of this digital material acknowledge that they have read and understood the MACRIS Information and Disclaimer (<a href="http://mhc-macris.net/macrisdisclaimer.htm">http://mhc-macris.net/macrisdisclaimer.htm</a>)

Data available via the MACRIS web interface, and associated scanned files are for information purposes only. THE ACT OF CHECKING THIS DATABASE AND ASSOCIATED SCANNED FILES DOES NOT SUBSTITUTE FOR COMPLIANCE WITH APPLICABLE LOCAL, STATE OR FEDERAL LAWS AND REGULATIONS. IF YOU ARE REPRESENTING A DEVELOPER AND/OR A PROPOSED PROJECT THAT WILL REQUIRE A PERMIT, LICENSE OR FUNDING FROM ANY STATE OR FEDERAL AGENCY YOU MUST SUBMIT A PROJECT NOTIFICATION FORM TO MHC FOR MHC'S REVIEW AND COMMENT. You can obtain a copy of a PNF through the MHC web site (www.sec.state.ma.us/mhc) under the subject heading "MHC Forms."

Commonwealth of Massachusetts
Massachusetts Historical Commission
220 Morrissey Boulevard, Boston, Massachusetts 02125
www.sec.state.ma.us/mhc

This file was accessed on: Friday, October 30, 2020 at 12:44 PM



## NON-CONTRIBUTING STRUCTURE INVENTORY FORM

NATIONAL PARK SERVICE - NAR/CRM List of Classified Structures (LCS) Program

117	100	A CONTRACTOR OF THE PARTY OF TH	1/4
1			
1 6 28		LE T	
		יון וייין	
			Samo
	A JANUARY	Ser.	
			A. P.
	Sammer 1		
			VVIII.
		7.	
			1.4
		PURITUES.	THE STATE OF
		HHIIII. I	761
		1111	LI TON
		1-411-1-1-1-1-1	THE A
		19/19/19/19	
			<b>3</b> 1
$\gamma_{c}$		1.1 = 1-	17 1
		1 1 1 1 1 1 1 1	
	die die	Manual E	C.
			W 1
		- Care	
1 1 1 1 1			
		P	
	FIFT /	EEED II	

Structure Number Existing IDLCS#?
4-107-B
PARK: MIMA State: M A
County: Middlesex
Structure Name(s): BURKE HOUSE GARAGE
55
Address or Location: 25 OLD BEDFORD RD.
CONCORD, MASS.
NPS Legal Interest:
Term Exp. Date:
Arch't./Eng'r./Designer:  Alterations (with dates):
Alterations (with dates).
Material(s): WD. SHINGLES, ASPHALT SHINGLE
CONCRETE PAD.
Condition: GOOD TAIR POOR
Setting: INACTIVE FARM YARD, ADJACENT

TO A DIRT SURFACE PRIVATE ROAD.

AND NERIAM'S CORNER

Recorded by: J. Glassman & P. Guthrie

Date (month/year): 2/93

 $\label{eq:historical} \textbf{HISTORICAL DATA:} \quad \textbf{Associated with the Burke house, adjacent.}$ 

DESCRIPTION: Gabled one-story two-car garage. Severe deterioration of the asphalt roofing shingles at the south-facing roof plane; wood shingles weathered. Missing garage doors. Otherwise, the structure is in fair to good condition. Concrete floor.

MANAGEMENT DATA: Leasable. Renovation work funded in FY 92 (for Burke House).