Massachusetts Cultural Resource Information System

Scanned Record Cover Page

Inventory No: CON.446
Historic Name: Helscher Barn

Common Name:

Address: 107 Spencer Brook Rd

City/Town: Concord

Village/Neighborhood: Bateman's Pond; North Quarter

Local No: E2-1566
Year Constructed: c 1817

Architect(s):

Architectural Style(s): Colonial Revival

Use(s): Agricultural; Out Building; Single Family Dwelling House

Significance: Agriculture; Architecture

Area(s): CON.CJ: Bateman's Pond Area II

Designation(s):

Roof: Wood Shingle

Building Materials(s): Wall: Wood; Wood Clapboard

Foundation: Granite; Stone, Cut; Stone, Uncut



The Massachusetts Historical Commission (MHC) has converted this paper record to digital format as part of ongoing projects to scan records of the Inventory of Historic Assets of the Commonwealth and National Register of Historic Places nominations for Massachusetts. Efforts are ongoing and not all inventory or National Register records related to this resource may be available in digital format at this time.

The MACRIS database and scanned files are highly dynamic; new information is added daily and both database records and related scanned files may be updated as new information is incorporated into MHC files. Users should note that there may be a considerable lag time between the receipt of new or updated records by MHC and the appearance of related information in MACRIS. Users should also note that not all source materials for the MACRIS database are made available as scanned images. Users may consult the records, files and maps available in MHC's public research area at its offices at the State Archives Building, 220 Morrissey Boulevard, Boston, open M-F, 9-5.

Users of this digital material acknowledge that they have read and understood the MACRIS Information and Disclaimer (http://mhc-macris.net/macrisdisclaimer.htm)

Data available via the MACRIS web interface, and associated scanned files are for information purposes only. THE ACT OF CHECKING THIS DATABASE AND ASSOCIATED SCANNED FILES DOES NOT SUBSTITUTE FOR COMPLIANCE WITH APPLICABLE LOCAL, STATE OR FEDERAL LAWS AND REGULATIONS. IF YOU ARE REPRESENTING A DEVELOPER AND/OR A PROPOSED PROJECT THAT WILL REQUIRE A PERMIT, LICENSE OR FUNDING FROM ANY STATE OR FEDERAL AGENCY YOU MUST SUBMIT A PROJECT NOTIFICATION FORM TO MHC FOR MHC'S REVIEW AND COMMENT. You can obtain a copy of a PNF through the MHC web site (www.sec.state.ma.us/mhc) under the subject heading "MHC Forms."

Commonwealth of Massachusetts
Massachusetts Historical Commission
220 Morrissey Boulevard, Boston, Massachusetts 02125
www.sec.state.ma.us/mhc

This file was accessed on: Friday, October 30, 2020 at 1:18: PM

FORM B - BUILDING

Boston, Massachusetts 02116

Assessor's number

USGS Quad

Arca(s)

Form Number

Massachusetts Historical Commission 80 Boylston Street

E2-1566

WESTFORD

The same			borho
T. C. S. L. S. L.	1		1
	HE		me . nt _
			inal 1stru
			uilde

od or village)

CONCORD

07 Spencer Brook Road

former Helscher barn

dwelling

barn

ca. 1817 ction


Owner's records

Col. Revival vernacular

unknown

Sketch Map

Draw a map of the area indicating properties within it. Number each property for which individual inventory forms have been completed. Label streets including route numbers, if any. Attach a separate sheet if space is not sufficient here. Indicate North.



Recorded by	A. Forbes research by David Dawson		
Organization _	for Concord Hist. Commission		
0.64	- 1 1000		

Date (month/day/year)

Exterior Material:	
2	fieldstone and granite
Foundation	
The state of the s	wood shingle
Wall/Trim	
	wood shingle
Roof	

Outbuildings/Secondary Structures _ stable/garage/barn

Major Alterations (with dates)_____

converted to dwelling ca. 1940 (see page 2). Windows and main door

Condition fair/good

Moved $\square x$ no \square yes Date $\underline{N/A}$

Setting _ Back from road on south side; Surrounded by lawn and mature trees

Barn and outbuildings to west, large meadow to southwest

ARCHITECTURAL DESCRIPTION

— see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings within the community.

This house, converted from a barn, is a 2 1/2-story, two-room deep structure, with an off-center chimney and a two-story rear wing. The facade is four bays wide. Most of the architectural embellishment is located at the off-center projecting lobby entrance, where a molded pediment surmounts a five-part transom, and a new 6-panel door is surrounded by a molded architrave and flanked by unfluted corner pilasters.

HISTORICAL NARRATIVE see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

This building was a barn, and was built, according to owners' records, in 1817. The accompanying farmhouse burned down early in this century, and in about 1940 it was converted to a dwelling by Betty and Jim Ford.

For most of the early 1900's this property, along with the former Wadley farm to the south and the Legross place just to the east, was owned by one of the area's many Scandinavian farmers, Martinus Helsher. He lived in the former farmhouse until it burned, and kept sheep in a barn that stood on the site of the present stable/garage.

BIBLIOGRAPHY and/or REFERENCES see continuation sheet

Maps, atlases: 1875 (?).
Keyes/Tolman "Houses in Concord." 1885; rev. 1915 and 1920's.
Town Directories and tax lists.
Interview with owner, 4/6/91.
Interview with neighbors, 7/92.

Recommended for listing in the National Register of Historic Places. If checked, you must attach a completed National Register Criteria Statement form.